

# Dismantling a Desktop Computer

A hooden ne bambò



Fa biribi bo wo ho ban <sup>1</sup>



Sɛ wobetutu afdie no a ɛnsò ehwɛ ansa <sup>2</sup>



Bere biara wobegye w'ahome no hohoro wonsa kama



Baabia wɛyɛ adwuma no siesie ho kamakama



Yi yi "screw" no nyinaa na deɛ efam ho no yi



Nhoma nhoma no kyekeyere ne nyinaa bo, nayi cables nyinaa



Yi "drive" no, bood, ɛnɛ "power unit" no nyinaa



Yi "aluminium" no firi bood no ho <sup>3</sup>



Tu waya bood no firi "hard disc drive" no ho



Bue "hard disc drive", <sup>4</sup> eye "screw driver" soronko a ɛhia. Deɛ ɔmanfoo taa pɛ paa ne "Torxsize 9"



Fa "screw driver" fa yi "magnet" unit no firi "magnet force" no ho



Yi nnaɛɛ nkonsonkonson "cop-per coil" no ansa na wahyɛases "hard disc drive" a wa tutu ako (a) "aluminium", (b) waya bood, (c) "magnet with steel shoes", (d) "copper", (e) "screws" <sup>5</sup>



Tutu "CD/DVD drive" na boa ano sɛwɔ "Printed" waya bood ena dadeɛ ne plastik



Tutu anyinam ahwoden



Yi "aluminium" ksee ne "steel/copper" firi nyinam ahooden no ho <sup>6</sup>



Boa boa nnooma wa tutu nyinaa ano akuo kuo (a) plastics, (b) ferrous metals, (c) printed wiring board, (d) aluminium, (e) cables, (f) mixed materials, (g) rare earth magnets <sup>7</sup>

Further information: [www.resourcefever.org](http://www.resourcefever.org)

1 Adwuma atadeɛ, wellington boots, nsa-gloves, akta-hwene, ne ahwehwe anuwa  
2 Plugging-ni, testing betumi asesa ama wo "electric" akwan hyia sɛ wotutu ɛnɛnɛm anti hɛwɛ yiyie  
3 "Recyclers" fo bi tumi yi "processor" ne "RAM" ɛton soronko  
4 "Steps 6-11" nso, wobetumi de ama "specialised companies" toforo  
5 "Case/platters" nso yi "aluminium" ɛnti ɛnhia sɛ wobetutu  
6 "Transformers, heat-sinks and large aluminium capacitors"  
7 Adwuma no nikonsoo ma "plastic, ferrous metals, cables" no iyi rbbaa no firi waye no ho